

CONTENTS

Chapter I

Overview of Concurrent Engineering

- 1.1 Desing
- 1.2 Approches of Concurrent Engineering
- 1.3 The meanning of Concurrent Engineering
- 1.4 Schemes for Concurrent Engineering
 - DFM Guidelines
 - Desing for Assembly
 - Computer-Aided DFM
 - Group Technology
 - Failure-Mode and Effect Analysis
 - Quality Function Deployment

Chapter II

Overview of DFA Software Package Program

- 2.1 Introduction
- 2.2 Desing for Assembly
- 2.3 DFA Question window
- 2.4 Question window (extended)
- 2.5 Question window for items (Basic DFA)
- 2.6 Graph window
- 2.7 Item library
- 2.8 Operations library
- 2.9 Formulas
- 2.10 Product information window
- 2.11 Product review window
- 2.12 Reports
- 2.13 Structure chart window
- 2.14 Table of subassembly

Chapter III

DFA Consideration of Easigard Post Assembly

- 3.1 Introduction
- 3.2 Easigard Post
- 3.3 Jackscrew subassembly for easigard post
 - Jackscrew
 - Bissell pin I
 - Bissell pin II
 - Top screw bearing
 - Top bearing inner support plate
 - Top bearing outer support plate
 - Top bearing distance washer
- 3.4 Assembly Sequence Chart
- 3.5 Implementing the model DFA software
- 3.6 Objective of the Research
- 3.7 Studing DFA Reports for Jackscrew subassembly
- 3.8 Decision
- 3.9 Application of the decision
- 3.10 Assembly sequence chart after redesign
- 3.11 Evaluation of DFA reports after redesign
- 3.12 Calculating amount of extra used material
- 3.13 Conclusion
- References

TABLES

Table 2.1, DFA questions window

Table 2.2, DFA questions window

Table 2.3, Items library window

Table 2.4, Operations library window

Table 2.5, Product information window

Table 2.6, Product review window

Table 2.7, Structure chart window

Table 2.8, Table of subassemblies

Table 3.1, Structured chart report (time)

Table 3.2, Structured chart report (cost)

Table 3.3, Production review report

Table 3.4, Suggestion for redesign report

Table 3.5, Responses report

Table 3.6, Structured chart report for jscrew2

Table 3.7, Product review table report for jscrew2

Table 3.8, Suggestion for redesign report for jscrew2

Table 3.9, Responses report for jscrew2

Table 3.10, New and former time

Table 3.11, New and former costs

Table 3.12, Savings and extra expenses

FIGURES

Figure 1.1, Traditional view of design

Figure 1.2, Nonlinear value function for weight

Figure 1.3, AHP hierarchy for concurrent engineering design

Figure 1.4, Concept of concurrent engineering

Figure 1.5, Product stages during concurrent design

Figure 1.6, Schemes for concurrent engineering

Figure 1.7, One-arm robot assembly station

Figure 1.8, Two-arm robot assembly station

Figure 1.9, Multi-station robot assembly system

Figure 1.10, QFD relationship matrix for a laptop computer

Figure 1.11, QFD house of quality for a laptop

Figure 3.1, Assembly sequence chart

Figure 3.2, Assembly sequence chart after redesign

DRAWINGS

- Drawing 3.1, Easigard Post
- Drawing 3.2, Jack screw subassembly for Easigard Post
- Drawing 3.3, J.Screw for easigard post
- Drawing 3.4, Bissell Pin I
- Drawing 3.5, Bissell Pin II
- Drawing 3.6, Top screw bearing
- Drawing 3.7, Top bearing inner support plate for easigard post
- Drawing 3.8, Top bearing outer support plate for easigard post
- Drawing 3.9, Top bearing distance washer for easigard post
- Drawing 3.10, Top plate
- Drawing 3.11, Top plate after changing
- Drawing 3.12, New and former first holl on J.screw
- Drawing 3.13, New and former second holl on J.screw
- Drawing 3.14, Top screw bearing for easigard post
- Drawing 3.15, J.screw for easigard post after changing
- Drawing 3.16, Top bearing inner support plate in changing
- Drawing 3.17, Top bearing inner support plate after changing
- Drawing 3.18, Top bearing inner support plate in changing
- Drawing 3.19, Top bearing inner support plate after changing
- Drawing 3.20, Jack screw for easigard post after changing